AL-V-B-093 Frost Log House Off Cash Valley Road Ca. 1850's

The building consists of a two story, three bay wide, "I" shaped structure. The building was originally made of log construction and probably a farm house judging from its location. Due to alterations and now completely covered with insul brick the building retains practically none of its original appearance.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME					
HISTORIC					
Frost Lo	g Cabin				
AND/OR COMMON					
2 LOCATION					
STREET & NUMBER					
	Valley Road				
CITY, TOWN	rarioy modu		CONGRESSIONAL DISTRI	СТ	
Corrigan	ville <u>X</u>	VICINITY OF	Sixth		
STATE	STATE		COUNTY		
Maryland			Allegany		
3 CLASSIFIC	ATION				
CATEGORY	OWNERSHIP	STATUS	PRES	ENTUSE	
DISTRICT	PUBLIC	_XoccuPIED	AGRICULTURE	MUSEUM	
_XBUILDING(S)	X PRIVATE	_UNOCCUPIED	COMMERCIAL	PARK	
STRUCTURE	вотн	WORK IN PROGRESS	EDUCATIONAL	X_PRIVATE RESIDENC	
SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	RELIGIOUS	
OBJECT	IN PROCESS	X_YES: RESTRICTED	GOVERNMENT	SCIENTIFIC	
	BEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL	TRANSPORTATION	
		NO	MILITARY	OTHER:	
NA ME	FPROPERTY rahame (trustee for A	lice Grahame)	Telephone #: 7	77-0287	
Rt. 1 Bo	x 116 B				
CITY, TOWN	CITY, TOWN			STATE, Zip code	
Cumberla	····	VICINITY OF	Maryland	21502	
5 LOCATION	NOF LEGAL DESCR	IPTION	Liber #: 149		
COURTHOUSE.			Folio #: 594		
REGISTRY OF DEEDS,	Allegany County		10110 π. >>-		
STREET & NUMBER	Allegally country				
	30 Washington St	reet			
CITY, TOWN		<u> </u>	STATE		
	Cumberland		Maryland	<u> </u>	
6 REPRESEN	ITATION IN EXIST	ING SURVEYS			
TITLE					
DATE		FEDERAL	STATECOUNTYLOCAL		
DEPOSITORY FOR SURVEY RECORDS					
CITY, TOWN			STATE		

CONDITION

CHECK ONE

CHECK ONE

_EXCELLENT

__DETERIORATED

_UNALTERED

__XORIGINAL SITE
__MOVED DATE_____

_GOOD

__RUINS

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Frost Log House is located off Cash Valley Road near Corriganville Allegany County.

The building basically consists of a two story, three bay wide, "T" shaped structure. The building was originally a log structure but now is completely covered with insul brick. A rear two story wing abuts the building on the northwest facade. Wall features are plain. The building is supported by a low, replaced concrete foundation with a plain water table. The roof of the building is both gable front and gable flank and is covered with asphalt shingles; replaced. In the peak of each gable are louvered ventilators. Eaves of the roof exhibit original boxed cornices with return ends and wide soffit. A gabled dormer is located on the west facade with boxed cornice with return ends and soffit with a diamond shaped ventilator in the peak of its gable. Windows in the building are double hung, with wooden sash frames and one-over-one. sixover-one, and six-over-six lights. Window trim is plain. There is one corbeled brick chimney in the building. It is replaced and located outside The main entrance is located on the southeast facade with replaced hardware. The building has two porches. One is a two-bay, open porch on the southeast facade covered with a flat roof with soffit and supported by short wooden columns. A portico with hip roof is located on the northeast facade supported by columns resting on high, brick bases.

The building is structurally sound but has been drastically altered since original construction and retains practically none of its original appearance.

8 SIGNIFICANCE

PERIOD	AF	REAS OF SIGNIFICANCE CH	IECK AND JUSTIFY BELOW	
PREHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	LAW	SCIENCE
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
1600-1699	XARCHITECTURE	EDUCATION	MILITARY	SOCIAL/HUMANITARIAN
1700-1799	ART	ENGINEERING	MUSIC	THEATER
X 1800-1899	COMMERCE	EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
1900-	COMMUNICATIONS	INDUSTRY INVENTION	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
SPECIFIC DAT	ES Ca. 1850's	BUILDER/ARCI	HITECT	

STATEMENT OF SIGNIFICANCE

The Frost Log House was originally a rectangular two story structure of log construction. Judging upon its location, this was probably a farm house built during the 1850's.

Farmers of the 19th century used the abundant forests of this area as a cheap and practical source of building material. The log walls have been concealed beneath insul brick and a two story addition to the rear of the house has altered the shape of the house. All hardware and roofs trim and the chimney have been replaced.

Once a reflection of the farmer's relationship with, and reliance upon his environment this house has been drastically altered since original construction. It retains practically none of its original appearance.

^{1.} Allegany County Land Records

^{2.} Harry Stegamier, Jr., Allegany County-A History (Parsons, W.Va.: McClain Printing, Co., 1976) p. 14

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Reocrds Cumberland, Maryland 21502

Stegmaier, Jr., Harry. <u>Allegany County-A History</u>. Parsons W.Va.: McClain Printing, Co., 1976

CONTINUE ON SEPARATE SHEET IF NECESSARY

GEOGRAPHICAL D		
ACREAGE OF NOMINATED PROPER	TY <u>5.73</u>	
VERBAL BOUNDARY DESCR	IPTION	
VERBAL BOOKBART BEGON		
LIST ALL STATES AND	COUNTIES FOR PROPERTIES OVERLAPPING S	STATE OR COUNTY BOUNDARIES
STATE	COUNTY	
STATE	COUNTY	
STATE		
EODA DEDADED	DV	
FORM PREPARED	DI	
	William Pratt, Dave Porsey	
ORGANIZATION	Tillian Flace, Save Soldey	DATE
	Historic Sites Survey	6/17/77
MITOGOLIA COULTEN		D/ 1////
STREET & NUMBER	IISCUITE SILES SUIVEY	TELEPHONE
STREET & NUMBER 507 National High		TÉLEPHONE 777-5967
STREET & NUMBER 507 National High CITY OF TOWN		TÉLEPHONE

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust


The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438

INVENTORY AO: AL-V-B-093	DATE: 6/17/77
REMODELING: <u>Drastic</u> , moderate, minor	149/594 5.73 Acres
NAME OF PROPERTY: Frost Log House	
LOCATION OF PROPERTY: Off Cash Valley Road	
DIRECTION DWELLING FACES: Southeast	
NAME OF OWNER: William C. Grahame (tru	stee for Alice G. Grahame, sister
ADDRESS: Rt. 1 Box 116 B	777-0287
Cumberland, Maryland 2	1502
SIGRIES: 1() 2(X) 3() 4() 5() 6() BAYS: 1() 2() 3(X) 4() 5() 6() 7(; ()
WINSS. ADDITIONS: Rear two story	
<pre>DWELLING SHAPE: (square, cross, rectangular)</pre>	T shaped"
WALL CONSTRUCTION:	
 () FRAME: Bevel, clapboard, weatherboard, woo () BRICK: Bond type - common, English, Flemish () STONE: Bond type - rubble, ashlar (random (X) LOG 	
(X) OTHER: Coverings Insul brick	
WALL FEATURES: Belt Course, Pilasters, Others	
FOUNDATIONS: High, Low, Brick, Stone Replaced	
WATER TABLE: None, Plain, Beveled, Moulded Brick	
	() 9/9() other(^X) 6/1 () narrow() mitred() pediment()
ENTRANCE, DOORS: LOCATION: Southeast HARDWARE: original() replaced() FAN LIGHT, TRANSOM, SIDE LIGHTS, F Paneled, Verticle, Horizontal Board	PLAIN
CORNICE, BARGE, EAVES: (crown, fascia, soffit, bed original (X) replaced() rafter ends, modillions,	d) B oxed cornice , dentils, frieze, architrave
ROOF: Gable front, Gable flank, Hip, Shed, Mansard HATERIAL: wood shingles, slate, tin, asphalt;	d, Gombrel, Flat, Dormors #_ original() replaced(X)
<pre>PORCHES: SHAPE OF ROOF - shed() hip(X) gable()</pre>	Flat
CHIMNEYS: Number: 1 Brick(X) Stone() Corbel Location: Flush end() Inside end()	
ARCHES: Door & Windows: Keystone, Flat, Segment	tal, Semicircular
COMMENTS:	
USE: Residence SIGNIFICANCE: Architecture	
DATE CONSTRUCTED: _{Ca.} 1850's CONDITION: Fair	

FLOCE PLAN:
() CENTRAL HALL: Two rooms, each side; double parlor, one side () SIDE HALL: One room deep, two rooms deep () IRREGULAR
STAIRWAYS:
 () ENCLOSED: Single flight, two flights with landing () OPEN: Single flight, two flights - one landing, three flights - two landings () DOG-LEG () DOG-LEG with WIADHAS () PIPAL () ALLIA
Weil Company of the C
() PLASTER () PANELED: original; replaced () BOARD PARTITION: baseboard, cornice, chair rail, wainscot
FIRI PLACES:
MUMBER
DOORS: paneled, board and batten, flush HARDWARE: original; replaced
DOOK & WINDOW TRIM:
 () PLAIN () ARCHITRAVE () SYMMETRIC with CORNER BLOCKS () FLUTED () FLUTED with CORNER BLOCKS () ARCHED OPENINGS: eliptical, tudor
NOTES:






A1-V-B-093 FROST LOG HOUSE OFF CASH VALLEY Rd JOHN E. NELSON 6/17/79 NORTHWEST



A1-V-B-093 FROST LOG HOUSE OFF CASH VALLY Rd JOHN E, NELSON 6/17/77 NORTH



A1-V-B-093 FROST LOG HOUSE OFF CASH VALLEY Rd JOHN E. NELSON 6/17/77 EAST